

**Below you will find a specification of the supply of products, which should be wet painted:**

- no corrosion or scale to prevent it, the products must first be cleaned.
- the space between the edges of the cut should be 1 mm
- the remnants of a laser cutting oxygen is removed by brushing or sanding
- parts, which are assembled or welded should be scoured before powder coating
- the holes are necessary for hanging the product but their location may be consulted
- any tape or their fragments must be removed. This also applies to each plastic parts that are not resistant to temperatures above 250<sup>0</sup>C
- in the case of plating before powder painting, the shell thickness must be specified,
- If products are ordered with the delivery, a request must be written (fax or mail)

The order must contain:

- Order number
- A sketch or drawing
- RAL color or number and gloss
- information if the product is to use external
- information whether the element should be painted one- or double-sided
- any special requirements for the quality
- the time and place of delivery